

3/3/2016

Scott County Board of Supervisors
Administrative Center 6Th Floor
600 West 4 Th Street
Davenport, Iowa 52801

Dear Board of Supervisors:

My name is Scott Bowman and I'm making a complaint against Magellan Pipeline for the repair work done on the line last fall. I have exhausted all attempts to resolve this matter with Magellan.

I'm now making an application with the Scott County Board of Supervisors in hope of a fair resolution to the property damage issue.

(1) SCOTT T. BOWMAN
12232 255TH STREET
DONAHUE, IOWA 52746

(PROPERTY DESCRIPTION OF DAMAGED LAND)

Sec:06 Twp:79 Rng:03PART W 1/2 NW 1/4COM 705.47'E NW CORNW NW: N89D52'E660'-
S0D10'W 2640.07' W 25'-N0D10'E 1320.01'- S89D52'W 635'-N0D10'E 1320' TO BEG 20.757AC SURVEY
24443-94

(2) * Magellan had no prior agreement to the work being performed.

* Magellan did not separate the subsoil material into a second parallel row from the topsoil row.

The soils were combined into one row. The damages that need to be resolved pertain to the compaction of the topsoil for many future years. (Pictures taken during process) Damages could not be worked out. Magellan mailed a check for \$1000.

IDOA Pipeline Construction Standards and Policies

All subsoil material that is removed from the trench will be placed in a second Windrow parallel to the pipeline trench that is separate from the topsoil windrow. In backfilling the trench, the stockpiled subsoil material will be placed back into The trench before replacing the topsoil.

The actual depth of the topsoil, not to exceed 36 inches, will first be stripped from the area to be excavated above the pipeline and from the adjacent subsoil storage area. The topsoil will be stored in a windrow parallel to the pipeline

trench in such a manner that it will not become intermixed with subsoil materials

- * No 24 hour notice was given before the work was started.
- * The working conditions were done in the rain. The ground was completely saturated.
- * After completion of the project, Magellan did no soil tillage or placement of a cover crop.
- * Magellan paid us less than the eventually agreed upon amount of \$1500 and late as work was completed in the fall and the check arrived in late January.

(3)

MAGELLAN MIDSTREAM PARTNERS L.P.

P.O. BOX 9123

WICHITA, KS 67277

**Contact Person*

ANDREW THOMAS

REAL ESTATE SERVICES

MEGELLAN MIDSTREAM PARTNERS L.P.

ONE WILLIAMS CENTER, MD OTC - 8

TULSA, OKLAHOMA 74172

Sincerely Submitted:

A handwritten signature in black ink that reads "Scott Bowman". The signature is written in a cursive style with a large, stylized "S" and "B".

Scott T. Bowman

12232 255th Street

Donahue, Iowa 528746

563-340-9373

slbowmans@yahoo.com

THE COUNTY AUDITOR'S SIGNATURE CERTIFIES
THAT THIS RESOLUTION HAS BEEN FORMALLY
APPROVED BY THE BOARD OF SUPERVISORS ON

DATE

SCOTT COUNTY AUDITOR

R E S O L U T I O N

SCOTT COUNTY BOARD OF SUPERVISORS

April 7, 2016

Approves the petition of Scott Bowman for a compensation commission to determine damages arising from the repair of pipeline

BE IT RESOLVED BY the Scott County Board of Supervisors as follows:

- Section 1. Scott Bowman has filed a petition with the Board making a complaint against Magellan Pipeline for the repair work done on a pipeline.
- Section 2. Mr. Bowman has exhausted all attempts to resolve this matter with Magellan Pipeline.
- Section 4. Per Iowa code Section 479.46, Mr. Bowman has submitted a petition with a description of damages which includes the offer for settlement.
- Section 5. The Board approves this petition to allow the landowner to commence proceeding by filing an application with the chief judge for the appointment of the compensation commission.
- Section 6. This resolution shall take effect immediately.